

Annexure – D

BUILDING SAFETY CERTIFICATE

No. 303

Dated : 22/05/2026

It is certified that the existing building **GOKULDAS PUBLIC SCHOOL** (name of the building or premises) at **BISTAN ROAD, KHARGONE** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3 GF, FF, SF	3 GF, FF, SF, Tower Roof	-	-	-	-

The building is owned/occupied by **GOKULDAS PUBLIC SCHOOL, KHARGONE** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of MPPWD (B/R) (Name of Department/Govt.) on 22/05/2026 (date of inspection) in the presence of Mr. ABHISHEK JAMRA (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 22/05/2026 for a period of 1 yr with rule and subject to compliance of the specific conditions as appended. years in accordance

1. Periodical inspection of school building must be ensured.
2. Time to time maintenance of school building must ensured.
3. —
4. —

Issued on 22/05/2026 at KHARGONE by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : ABHISHEK JAMRA Sub-Divisional Officer,

Name : ABHISHEK JAMRA (B&R). Sub-Division
KHARGONE (M.P.)

Designation : SUB-DIVISIONAL OFFICER

Name & Address of Department/ Office: KHARGONE